## **Notice of Completion**

## WARNING:

Regulation I, Section 6.09(a), requires that the owner or applicant notify the Agency of the completion of the work covered by the application and when its operation will begin. This form is provided for your convenience to assist you in complying with this part of the Regulation.

| or me Kegui               | ation.                          |                           |  | <u> </u>                 |                |
|---------------------------|---------------------------------|---------------------------|--|--------------------------|----------------|
| APPLICAN                  | IT or OWNER SECTION             |                           | <u> </u>   |                          |                |
| Mail to:                  | Puget Sound Air Polls           | ation Control Agency      |  |                          |                |
| Man w.                    | Plan Review Section             | nuon control rigonoy      |  |                          |                |
|                           | 110 Union Street                | Suite 500                 |  |                          |                |
|                           | Seattle, Washingt               |                           | *  |                          |                |
|                           | Scattle, Washing                | .01 70101-2050            |  |                          |                |
| <b>~</b> .1               |                                 |                           |  |                          |                |
| Gentlemen:                |                                 |                           |  |                          |                |
| The project               | described below was com         | pleted on MAY 25, 19      | 994  | •                        |                |
|                           | 11116                           |                           |  |                          |                |
| Cera                      | lelf //k Jun-                   | SAFE'                     | TY/ENVIRONMENT   | AL MGR. 623-559          | 6 6/14/94      |
| Sign                      | nature of Owner and/or Applican | nt                        | Title  | Phone                    | Date           |
|                           |                                 |                           |  |                          |                |
|                           |                                 |                           |  |                          |                |
| FOR AGENCY USE ONLY       |                                 |                           |  | Notice of Construc       | ction No. 5351 |
| Project Description       |                                 |                           |  | Registration No.         | 11339          |
| •                         | <u> </u>                        | ve e puo t                |  |                          |                |
| Une DCL F                 | S-175 Bagnouse at 1,000         | cfm for Rail Car Loading  | <b>J.</b>  |                          | Conditions On  |
| A==1!                     |                                 | is a                      | 0  |                          | Reverse Side   |
| Applicant                 | •                               |                           | Owner  |                          |                |
|                           | LD BROWN                        |                           |  |                          |                |
|                           | ROVE CEMENT COMPANY             |                           | ASH GROVE CEMENT COMPANY (E MARG,) 3801 E MARGINAL WY S, SEATTLE, WA, 98134-1113 |                          |                |
| 3601 E                    | MARGINAL WY S, SEATT            | LE, WA, 90134-1113        | 3001 E MARGINA   | L WI S, SEATTLE, WA, 961 | 34-1113        |
| Location                  |                                 |                           |  |                          |                |
| ASH G                     | ROVE CEMENT COMPANY             | (E MARG,), 3801 E MARGINA | al wy s, seattle, wa,  | 98134                    |                |
| Inspector check Engineer_ |                                 |                           | A  | and Inspector check      |                |
| Follow-up                 |                                 | _                         |  | (Estimated completion D  | ate Plus 7)    |
|                           |                                 |                           |  |                          | ŕ              |
| Date Inspect              | .ed                             |                           | Inspector  |                          |                |
| REMARKS                   |                                 |                           |  |                          |                |
|                           |                                 |                           |  |                          |                |
|                           |                                 |                           |  |                          |                |
|                           | <del></del>                     |                           |  |                          |                |
|                           |                                 |                           |  |                          |                |
|                           |                                 |                           |  | <u> </u>                 |                |
|                           |                                 |                           |  |                          |                |
|                           |                                 | □ See                     | Attachment   |                          |                |

mej Form 63-11.1, (1/89)